

TE-719 AGT

CLASSIFIED MESSAGE

25X1A

CRIG : [REDACTED] Case 2001/07/24 : CIA-RDP64B00187A000700120014-5
 UNIT : CONTRACTS BR., DPD
 EXT : 4116
 DATE : 14 APRIL 1960

ROUTING	
1200 14 SEP /DPD	4 OPS /DPD
2 DD/P	5 OSS /DPD
3 A/CN /DPD	6 SEC /DPD
	7 MAT /DPD
	8 RI /DPD
	9 XX
	10 XX

25X1A

TO : [REDACTED]

FROM : DIRECTOR

CONF : DPD (1,2,3,4,5,6,7,8,9,10)

INFO : S/C (11)

RR

TOR: 2027Z 15 APR 60

POLICY	DEFERRED	PRIORITY	INITIALS
X	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

OUT65186

25X1A

TO : [REDACTED]
25X1A

INFO

25X1A

SITE : [REDACTED]

580



WILL VISIT [REDACTED] AND [REDACTED] 5X1A

21 APRIL TO DISCUSS HELMET DEVELOPMENT AND EQUIPMENT REQUIREMENTS.

END OF MESSAGE

25X1A

DOCUMENT NO. 19
 NO CHANGE IN CLASS. X
 DECLASSIFIED
 CLASS. CHANGED TO: TS S C
 NEXT REVIEW DATE: 2011
 AUTH: HR 70-3
 DATE: 020681 REVIEWER: 010956

OPS/DPD 
 SEC/DPD 
 MAT/DPD 

COORDINATING OFFICERS

CHIEF, CONTR., BR., DPD
 RELEASING OFFICER

SECRET

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

C/DB
11

DATE 0044Z 18 NOV 60

S E C R E T

MB
ops

R1

TO : DIRECTOR

25X1A

RECDON DPD (1,2,3,4,5,6,7,8,9,10)

DOCUMENT NO. 17

ROUTINE

INFO : S/C (11)

NO CHANGE IN CLASS.

 DECLASSIFIED

CLASS CHANGED TO: TS S C

NEXT REVIEW DATE:

AUTH: HR 70-2

DATE: 0206 REVIEWER: 010958

IN 37067

TDR: 0044Z 18 NOV 60

25X1A

25X1A

59 52

25X1A

REF

4941 (OUT 75382) W

CONTRACTS

25X1A

1. HELMET S-392 WAS TRANSFERRED FROM [REDACTED] PRIOR ARRIVAL OF PRESENT P-E STAFF.

A. DATE UNKNOWN, PROJECT PROGRESS REPORTS ON FILE FOR HELMET S-392 NUMBER 7 TOTAL, NBR 1 IS DATED 14 JUNE 60. ITEM MAY HAVE BEEN RECEIVED EARLY JUNE 60.

B. RESUME OF P.P.R'S: NBR 1 UNCOMFORTABLE FIT; SHELL REDESIGN REQUIRED; INHALATION AND EXHALATION VALVE LEAKAGE; VALVE COUNTER PRESSURE LINE FLOW STOP-PAGE; EXCESSIVE WEAR ON VISOR SEAL PLUNGER. VISOR HEATING SUPERIOR TO MA-2. DONNING CHARACTERISTICS SUPERIOR TO MA-2. NBR 2 REPAIRING OF INOPERATIVE COMPONENTS. NBR 3 DAMAGE TO VISOR HEATING CONDUCTOR; FROST ACCUMULATION ON VISOR DURING FLIGHT. USE OF THIS VISOR DISCONTINUED DUE TO ELECTRICAL ARCING. NBR 4 P.P.R. INDICATES NO PROGRESS. NBR 5 HELMET RETURNED TO CLARK CO BY [REDACTED]

25X1A

[REDACTED] FOR MOD AS NECESSITATED BY PREVIOUS EVALUATION. NBR 5

S E C R E T

25X1A

S E C R E T

[REDACTED] 5952 (IN 37067) PAGE TWO
[REDACTED]

6 AND 7, NO PROGRESS THIS PERIOD.

C. AFFIRMATIVE. RETURN DATE O/A 12 JUL 60. REDELIVERY
NOT MADE.

D. ASSUME PRESENTLY AT DAVE CLARK CO.

E. NONE DUE TO UNFAMILIARITY (SEE PARA 1 ABOVE) RE-EVALUATION
OF S-892 MAY BE ACCOMPLISHED AT [REDACTED] IF HQS DESIRES.

25X1A
THIS PLAN IF ACCEPTABLE, COULD BE PURSUED ONLY AFTER MANUFACTURERS
SATISFACTION OF CHANGES AS RECOMMENDED BY PREVIOUS PHYSIOLOGIST.

END OF MESSAGE

S E C R E T